

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

JH1332
NNW
> 1
1.697 mi.
8958 ft.

UNDER GROUND
BAY PARKWAY AND 86
BROOKLYN, NY

NY Spills S124518263
N/A

Site 2 of 5 in cluster JH

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: UNDER GROUND
Address: BAY PARKWAY AND 86
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1903136 / Not Reported
Facility ID: 1903136
Facility Type: ER
DER Facility ID: 541258
Site ID: 591090
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2019-06-26
Investigator: Con Ed Unassigned
Referred To: Not reported
Reported to Dept: 2019-06-26
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2019-06-26
Spill Record Last Update: 2019-06-27
Spiller Name: ROB DUFFY
Spiller Company: CON ED
Spiller Address: BAY PARKWAY AND 86
Spiller Company: 999
Contact Name: ROB DUFFY
DEC Memo: "Emis # 272433 6/27/19-Zhune spoke to ERT-Robert Duffy. Robert said they found 4 gallons of unknown oil in the structure. When they were cleaning the structure they noticed ground water coming into the structure through a crack. The structure has been cleaned. They have to replace the transformer. "

Remarks: "clean up is done"

All Materials:

Site ID: 591090
Operable Unit ID: 1338713
Operable Unit: 01
Material ID: 2348216
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 4.00
Units: G
Recovered: Not reported
Oxygenate: Not reported